



NOTES:

1. EXERCISE CAUTION WHEN BENDING NYLON RETAINER DURING ASSEMBLY OF LEVERS TO PREVENT PERMANENT DEFORMATION OF THE RETAINER.
2. FOR MOTOR RATED 2 R.P.M.;S, USE SWITCH PARTS FOR LOWER R.P.M.
3. CONTACT COMPRESSION .12 MIN .22 MAX .

SWITCH ASSY NO.	POLES	FREQ	RPM	CUTOUT RPM MIN	MAX	SPRING	LEVER/WGT ASSY	SWITCH BRACKET ASSEMBLY
36RS2050	2	50	2850	2150	2550	RS4501A02	RS2001A02	RS5002A01
36RS2060	2	60	3450	2600	3100	RS4501A07	RS5003A05	RS5002A01
36RS4050	4	50	1425	1075	1300	RS4501A01	RS5003A02	RS5002A01
36RS4060	4	60	1725	1300	1550	RS4501A01	RS5003A03	RS5002A01
36RS6050	6	50	950	700	850	RS4501A01	RS5003A04	RS5002A01
36RS6060	6	60	1140	850	1000	RS4501A03	RS5003A01	RS5002A01
36RS8060	8	60	850	650	775	RS4501A03	RS5003A04	RS5002A01
36RS8050	8	50	710	550	660	RS4501A02	RS5003A04	RS5002A01
36RS2061	2	60	3450	1750	2150	RS4501A03	RS5003A05	RS5002A01
36RS2062	2	60	3450	1850	1950	RS4501A02	RS5003A05	RS5002A01

REV. DESC: + SWITCH ASSY NO. 36RS2062			
REV. LTR: F	BY: JMF	REVISED: 16:08:51 12/05/2002	TDR: 288349
FILE: AAA00054022		REF: 36RS	
MTL: -			

BALDOR ELECTRIC Co.

ROTATING SWITCH ASSY-36 MOTORS